

White

Amazing Casting Resin

72D White Urethane

Product Description:

Alumilite's White also known as Amazing Casting Resin provides users with an extremely user-friendly rigid urethane that has good overall physical and cosmetic properties. The low viscosity along with the white appearance makes this material ideal for users who are looking for perfect cosmetics in their castings. The material has a mixed viscosity less than 100 cps and a mix ratio of 1:1 by weight or by volume. The material features a 2-minute open time and transitions from clear to opaque white to let the user know when the pot life is expiring. Demold time typically ranges from 5 to 10 minutes depending on the mold temperature and the mass of the material being cast. We always recommend warming the mold before casting to achieve a more consistent and thorough cure.

Physical Properties:

Color	White
Mixed Viscosity (cps)	90
Hardness, (ASTM D-2240) Shore D	72
Specific Gravity	1.05
Shrinkage (in/in)	.006
Tensile Strength (ASTM D-638) (psi)	4,500
Elongation (in/in)	10%
Heat Deflection (ASTM D-648) (Degrees F)	185
Izod Impact (ASTM D-256) (lb/in)	.40
Compression (psi)	6,000

General Properties:

Color	"A" Side	Clear
	"B" Side	Translucent Yellow
Mix Ratio		1:1 by wt. or vol.
Shelf Life		1 year
Open Time at 75 Degrees F (100g mass)		2 minutes
Demold Time at 75 Degrees F (100g mass)		5-10 minutes
Full Cure Schedule		72 hours

Packaging:	16 oz	
	32 oz	
	2 gal	8 lbs A/8.6 lbs B
	10 gal	39 lbs A/45 lbs B
	Drum Kit	411 lbs A/465 lbs B

Safety: Read complete labels, SDS, and technical data sheet including instructions before using.

Instructions

Keep Alumilite out of the reach of children, do not take internally, and do not use in any way other than it's intended use.

Before Starting

Make sure your work area is appropriate for measuring, mixing, and pouring casting resins that can and will stain any porous materials such as carpet and clothing. Also, make sure to use and store materials in an area where children cannot reach or access.

1. Mold Preparation

Before mixing and pouring the resin into your mold to achieve a cast resin piece there are a few things you can do to prepare your mold that will greatly enhance the physical properties and curing of your cast resin piece.

The first thing you can do is to preheat your mold. Warm the mold in a conventional oven at 120-150 degrees F for 15 minutes or warm your mold in a microwave for 1 minute/lb of rubber on high. This will only warm your mold and will not affect the microwave or your mold adversely. It will, however, help the thin sections of your casting cure more evenly with larger sections and reduce your demold time. It will also help the resin set up uniformly to give you a consistent fully cured cast piece. (It is highly recommended to warm your molds when using the Slow Set, Water Clear, Clear, Flex, Amazing Clear Cast, or parts under a 1/2" in thickness to ensure proper curing.)

Note: Do not microwave when there is resin in the mold, if you have painted your mold, or if you have already coated the mold with the Metallic Powders.

2. Eliminating and Avoiding Air Bubbles

To release surface tension and help with minimizing unwanted air bubbles in difficult to fill areas, baby powder your mold prior to casting. Painting or sprinkling baby powder on all the surfaces inside your mold will greatly reduce the amount of surface tension in the mold. As the resin flows into the mold it will physically pick up each particle of the baby powder and will help keep the air bubbles away from the surface of the mold where they can be seen in your finished part. The powder will not change the appearance of your casting. Since the resin picks up and absorbs the baby powder, the white color of the powder will not show up in your finished piece. If you have a small paintbrush, simply paint in the baby powder and knock out the excess before casting your part. (Baby powder not recommended when pouring clear parts.)

Warming your mold and baby powdering it prior to casting your piece will greatly enhance the physical properties and appearance of your cast piece by helping it cure properly and aiding in the prevention of air entrapment.

3. Mixing

Before mixing make sure you know the proper mix ratio of the material you are using. Double-check the mix ratio. The mix ratio of Alumilite White is 1:1 by weight and/or by volume. It's important to note and understand mix ratio by weight (with a scale) or by volume using a graduated cup. Please check each individual material you use as some are mixed only by weight or by volume. Varying the mix ratio of Alumilite resins will alter the cure and negatively change the physical properties and is NOT recommended. Alumilite resins have been formulated to crosslink completely and altering the mix ratio may leave uncured components in your cast piece that could come out at a later time.

We recommend you mix at least half an ounce of each side to ensure you have a proper mix ratio. If you measure out 1/4 of an ounce of A in one cup and 1/4 ounce of B in another and dump the A into the B you will be off ratio due to the residue left in the A side cup. In larger amounts of resin batches, this will not be enough to throw off the mix and cause an issue with the resin setting up. But with small amounts of resin (1/4 oz of each side) this will be enough to affect the mix ratio and will typically result in parts that appear darker in color and remain soft (never harden).

Once the materials have been measured out in separate cups, the preferred method of pouring one into another, to decrease the amount of air introduced, is to pour the A side into the B side. Smooth sided, flat bottom cups are preferred for effective mixing. Do not use Styrofoam.

After the materials have been poured together, mix vigorously (keeping the stir stick in contact with the bottom of the cup - reduces air from being introduced into your resin) for approximately 15-25 seconds. Make sure to scrape the sides and the bottom of the mixing cup.

4. Pouring

Once the material is thoroughly mixed, pour the resin slowly down the side of your mold cavity. Tilting your mold will prevent the resin from splashing in the bottom of your mold and creating unwanted air bubbles that would then need to find their way to the top of the mold. Similar to tilting your glass as you pour a beverage rather than letting it splash/cavitate off the bottom creating air bubbles.

Squeezing the brim of the cup to form a point allows you to pour a smaller/slower stream of resin into your mold controlling the flow and reducing the chance of unwanted air bubble entrapment against the surface of the part.

If your mold has undercuts, pour enough resin into the mold to fill it halfway. Then, tilt and rotate the mold in the opposite direction of the undercut to allow the air to escape up the side of the mold. Squeezing or burping the mold at the same time will also help relieve the air trapped in the undercut and allow the bubbles to release from the mold surface. Once you see air bubbles come to the surface of the resin and you can be confident you have removed the air from the undercut, simply top off the mold by pouring the remaining resin into the mold.

5. Open Time

Alumilite White (Amazing Casting Resin) has an Open Time of 2 minutes at 75 Degrees F (100g mass). Larger amounts of mixed resin will shorten your work time. As warmer ambient room temperature will also shorten work time. To increase the open time of Alumilite resins, simply chill the "A" & "B" sides of the Alumilite in the refrigerator or in a bucket of ice for approximately 30 min. before pouring. This will increase the open time of the Alumilite White by 30-60 seconds. When cooling your resin, we highly recommend preheating your mold to ensure a proper cure.

6. Color – Dyes & Painting

Alumilite casting resins can be dyed or pigmented using non-water based dyes. Alumilite offers a line of translucent dyes in standard colors that react/crosslink chemically with the resin to achieve beautiful colored resin cast pieces with no worry of leaching or color ever coming out of the cured piece. Alumilite also offers Fluorescent colored dyes to achieve brighter colors in your casting. Use a maximum of 5% dye into the A side of the to achieve bright and solid colors. If you wish to preload the dye into the Alumilite White to achieve consistent colors in every cast, add the dye to the A side and mix thoroughly. If you are looking to use a dye, pigment, or filler that you have not used before, we highly recommend making a small test sample to ensure compatibility before using or preloading into the resin.

Painting can be achieved but is best if painted immediately after demolding while the resin is still curing. Once the resin has completely cured and hardened up, paint adhesion is not as strong. Most paints will still bond but may scratch off easier if not applied while the resin is still curing. Another option is to paint your silicone rubber mold, allow the paint to dry, and then cast your resin into the mold. Alumilite resins will chemically bond to the dry paint, and once the resin cures you will demold a perfectly painted piece.

7. Mold Release

To achieve maximum parts out of your silicone molds or to ensure release out of non-silicone molds (aluminum, urethane elastomers, latex, or any other substrate), we recommend using Alumilite's Stoner Urethane Mold Release. This offers maximum release and puts an effective layer of release on non-porous surfaces to release Alumilite Casting Resins. When using the Stoner Mold Release, some release will transfer to the cast resin part after demolding and may interfere with the ability to paint or bond the cast resin piece. A mild solvent wash and perhaps even some mild abrasion may be required to remove the Stoner from the casting.

Alumilite does offer a "Paintable" mold release called UMR. UMR can be used as a release between silicone to silicone, urethane to urethane, silicone to urethane, and much more. It is an all-purpose mold release that does not interfere with painting unless excessive amounts are used and transferred to your casting.

8. Shelf Life

The shelf life of Alumilite White is 1 year in an unopened container but a much longer shelf life can be expected even after being opened as long as it is sealed and stored in an area free from moisture contamination (humidity and changing of temperatures such as a garage).

9. Moisture Contamination

Relative humidity or moisture will react with the B side of Alumilite White and crystalize. You may notice crust, crystals, or chunks around the tip or cap or at the bottom of the bottle. If the B side shows signs of moisture contamination, you may need to strain the chunks or crystals with a paint filter or screen to remove them from the resin. Once strained, the B side can be used as normal. However, if the A side has been contaminated by moisture, it will not show any signs of contamination until you cast your piece in which you will notice an excessive amount of bubbles or perhaps even a froth or foam on the top side of your casting. Once the polyol side (A side of Alumilite White) has been contaminated with moisture it is extremely difficult to restore. Vacuuming the resin for a long period of time may vaporize and pull the moisture out or a molecular sieve can be mixed in and allowed to react and settle to the bottom with some success. The absolute best solution is to place caps and lids back onto the containers as soon as you are done measuring the material you need to pour and storing in an environmentally controlled space that contains low humidity.

10. Work Area & Clean Up

Mixed Alumilite resins will absorb into porous materials and will stain! Avoid clothing, carpet, upholstery, and any other porous materials which will stain and will not come out. Resin casting is best done in a designated work area such as a basement, garage, or hobby room with adequate air movement or ventilation. Cover any surfaces including floors with plastic sheeting, cardboard, or plywood to prevent damage from spilled resin. To clean up unmixed or still liquid material, use rubbing alcohol on a rag or paper towel to quickly clean and remove. Once cured, the resin is extremely durable and chemical resistant and nearly impossible to remove.



There are a couple of solutions out in the market that claims to dissolve cured urethanes. If you require such material, please call us and we can refer you to some possible solutions.

11. Warranty

NO WARRANTY OF MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE OR ANY OTHER WARRANTY, EXPRESS OR IMPLIED, IS MADE CONCERNING THE INFORMATION HEREIN PROVIDED OR ANY RELATED PRODUCT. The user is responsible for determining whether the Alumilite product is fit for user's particular purpose and suitable for user's use or application. Given the variety of factors that can affect the use and application of an Alumilite product, the user must determine the suitability of the product for its intended application, and user assumes all risk and liability for safe use of the product. Alumilite's liability is limited to product replacement only after review/testing of the product alleged to be defective that is returned to Alumilite in accordance with Alumilite's Shipping and Returns Policy. In no event shall Alumilite be liable for punitive, consequential or indirect damages or damages in excess of the purchase price of the product.